



Universal
Specialist in Rotating Electrics



TECHNICAL UPDATE

Ignition switch problems with Mercedes, Nissan, Opel, Vauxhall and VW applications!

Please note that the following part numbers will now be supplied with a warning sticker attached to the part:

UNS207-VW

UNS548-Mercedes

UNS597-Mercedes

UNS641-Mercedes

UNS647-Mercedes

UNS681-Vauxhall

UNS805-Vauxhall

UNS820-Vauxhall

UNS1001-VW

UNS1039-VW

UNS1076-Nissan

UNS1153-Nissan

UNS1215-Mercedes

UNS1218-Vauxhall

UNS1219-Mercedes

UNS1318-Mercedes

UNS1327-Nissan

UNS1359-Vauxhall

We have found that the above manufacturers have ignition switch problems on certain models. The switch is sending a live feed to the starter motor even when the switch is in the return position. This is causing the starter motor to continuously engage and consequently it will eventually burn the starter motor out.

The ignition switch must be tested or replaced before the starter motor is installed!

If you need any further information please contact our technical department on; 01268 662210

All part numbers and pictures are used for reference purpose only.
Offer 303 11/09